

City of Puyallup Building Division 333 S. Meridian, Puyallup, WA 98371 (253) 864-4165 www.cityofpuyallup.org

INSPECTION REPORT

Date of Inspection:	Jul 17, 2024	Inspection Result:	PASSED
Permit Number: Property Address:	PRFO20231761 1023 39TH AVE SE, PUY/	allup, wa 98374;	
	HOWARD S WRIGHT 415 1ST AVE N SEATTLE, WA 98109 Installation of two exterior concrete pads for standby diesel generators - CENTERIS VOLTAGE PARK		

On this day we have inspected your construction for **Building Final Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

Comments:

Corrections:

Sincerely,

King

Shannon King Building Inspector 2 ShannonK@PuyallupWA.gov (253) 840-6684