

City of Puyallup **Engineering Division** 333 S. Meridian, Puyallup, WA 98371 (253) 864-4165 www.cityofpuyallup.org

INSPECTION REPORT

Date of Inspection:	Jul 25, 2024	Inspection Result:	PARTIAL PASS
Permit Number: Property Address:	PRGR20240491 3112 E PIONEER, PUYALLUP, WA 98372; 911 SHAW RD, PUYALLUP, WA 98372; 901 SHAW RD, PUYALLUP, WA 98372; 813 SHAW RD, PUYALLUP WA 98372;		
	Grading for relocat	ES, LLC PO BOX 5 ENUMCL ion and restoration of an exi . STREAM RELOCATION - EA	sting stream at the East

On this day we have inspected your construction for **Engineering Daily Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

Comments: McKee had already stripped south of the silt fence that was already installed by the time I arrived onsite. They have added silt fence 5' off of the existing culvert heading to the pond. I instructed them to finish installing the silt fence since everything was ready to go. I also instructed them to get some straw and pack it into the disturbed soils caused buy keying in the fence. I informed them once the silt fence was in and soils have been stabilized they must install all outlet protections as stated on page C1.0 of the plans.

Corrections:

Sincerely,

Jeff Hill Development Engineering Inspector Jhill@PuyallupWA.gov (253) 204-5633