



City of Puyallup

Engineering Division

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

www.cityofpuyallup.org

INSPECTION REPORT

Date of Inspection: Jul 25, 2024

Inspection Result: **FAILED**

Permit Number: PRGR20240491

Property Address: 3112 E PIONEER, PUYALLUP, WA 98372; 911 SHAW RD, PUYALLUP, WA 98372; 901 SHAW RD, PUYALLUP, WA 98372; 813 SHAW RD, PUYALLUP, WA 98372;

Contractor: MCKEE ENTERPRISES, LLC PO BOX 5 ENUMCLAW, WA 98022

To construct: Grading for relocation and restoration of an existing stream at the East Town Crossing site. STREAM RELOCATION - EAST TOWN CROSSING

On this day we have inspected your construction for **Erosion And Sediment Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

Comments: No out let protection installed through out the site. McKee has stripped up to 5' of the culvert leading to the pond. There is a substantial amount of water running though this culvert and in a rain event runs the chance of over flowing into the cut area. Corrective actions should be taken immediately.

Corrections:

- 1 install out let protection as stated on page C1.00 of the approved plans

Sincerely,

Jeff Hill
Development Engineering Inspector
Jhill@PuyallupWA.gov
(253) 204-5633