



City of Puyallup

**Building Division**

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

[www.cityofpuyallup.org](http://www.cityofpuyallup.org)

## INSPECTION REPORT

**Date of Inspection:** Aug 08, 2024

**Inspection Result:** **FAILED**

**Permit Number:** PRDE20240877

**Property Address:** 4102 S MERIDIAN, Unit: D, PUYALLUP, WA 98373;

**Contractor:**

**To construct:** Demolition and removal of existing entry feature element and interior spaces (offices/restrooms facilities) associated with previous tenancy, and related site work as required for patch and repair of non-conforming adjacent areas. ~ SOUTH HILL CTR- SPACE #10 DEMO

On this day we have inspected your construction for **Erosion And Sediment Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

**Comments:** Prior to the rain starting the parking lot storm will need to be jetted and vaced. Demo debris is being washed into the storm system. While front of storm is being washed, the traces through the parking lot need to be washed as well. Dig out the NE corner of the parking stall where the curb cut is located. This will allow proper flow into the drainage basin. Please schedule a E&S inspection "DURING" the storm cleaning process.

Also, still need to verify sewer cleanliness from the inside demo!

**Corrections:**

- 1 - Demo debris needs to be cleaned up prior to rain.
- Maintain storm run off cleanliness.
- Chip concrete away from SS c/o prior to next inspection.
- Keep interior demo debris out of sewer plumbing.

Sincerely,



City of Puyallup

---

**Building Division**

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

[www.cityofpuyallup.org](http://www.cityofpuyallup.org)

Jason Little  
Development Engineering Inspector  
[JLittle@PuyallupWA.gov](mailto:JLittle@PuyallupWA.gov)  
(253) 435-3636