City of Puyallup

Engineering Division

333 S. Meridian, Puyallup, WA 98371 (253) 864-4165 www.cityofpuyallup.org

INSPECTION REPORT

Date of Inspection: Aug 14, 2024 Inspection Result: PARTIAL PASS

Permit Number: PRFUP20231536

Property Address: 1006 39TH AVE SE, PUYALLUP, WA 98374;

Contractor: PSE - INFRASOURCE 3130 S 38TH ST TACOMA, WA 98409

To construct: PERMIT EXT TO 12/29/2024 109145875 - Gas Main remediation - Install

1598' of 2" gas main, we will replace 8 services and install 7 test sites (T&T). Sidewalk was considered but not enough room for our gas utilities to be safely installed requesting hard surface cuts - detailed in

restoration plan. Work is primarily on 10th St SE.

On this day we have inspected your construction for **Close All Restoration Complete Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

Comments: Concrete restoration has been completed.

See corrections below.

Corrections:

- 1 Schedule dental parking lot asphalt restoration 48hrs prior to work.
 - Schedule 48hrs prior to work for intersection of 39th and 10th asphalt patch and G&O.
 - Intersection of 39th and 10th will need to be two separate nights. 1st night will be patch AND replacement of MH frame and cover (supplied by city) and GV housing set to grade with thickened asphalt and pave around monument. 2nd night will be G&O.

Note: Please have white temp tape on site!

- Areas where services were installed need to be touched up with top soil, raked out, and grass seed installed. Where there is heavy sand at the surface, remove it and place top soil. Rake the seed in.


Sincerely,



City of Puyallup

Engineering Division

333 S. Meridian, Puyallup, WA 98371 (253) 864-4165 www.cityofpuyallup.org



Jason Little
Development Engineering Inspector
JLittle@PuyallupWA.gov
(253) 435-3636