



City of Puyallup

Building Division

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

www.cityofpuyallup.org

INSPECTION REPORT

Date of Inspection: Aug 20, 2024

Inspection Result: NOT READY

Permit Number: PRCTI20240784

Property Address: 1023 39TH AVE SE, PUYALLUP, WA 98374;

Contractor: HOWARD S WRIGHT 415 1ST AVE N SEATTLE, WA 98109

To construct: Interior tenant improvement to construct UPS & Battery Rooms totaling 1,753 sf - CENTERIS SCALE MATRIX UPS & BATTERY ROOM TENANT IMPROVEMENT

On this day we have inspected your construction for **Frame Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

Comments:

Corrections:

- 2 1; Provide City approved plans or r.f.i. at time of framing inspection for new ups room mechanical penetration of wall.

Sincerely,

Shannon King

Building Inspector 2

ShannonK@PuyallupWA.gov

(253) 840-6684