



City of Puyallup

Building Division

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

www.cityofpuyallup.org

INSPECTION REPORT

Date of Inspection: Aug 23, 2024 **Inspection Result:** **NOT READY**

Permit Number: B-20-0180

Property Address: 3601 9TH ST SW, PUYALLUP, WA 98373;

Contractor: THARALDSON HOSPITALITY DEV LLC 4520 36TH AVE S FARGO, ND 58104 Roger Olson 4520 36th ave s fargo, ND 58104 (701) 850-9953

To construct: HOMEWOOD SUITES SOUTH HILL MALL MOTEL *FEE DEFERRAL-SWR*
REVISION (1) 6/8/2023 - VALUE ENGINEER FOOTINGS AND ADD PERIMETER DRAINTILE

On this day we have inspected your construction for **Frame Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

Comments:

Corrections:

- 1 date of inspection 8/22/2024
framing of 4 floor east to west corridor and north to south to elevator
- 1.complete fire stop
- 2.secure all loose wires hanging out of the ceiling
- 3.secure all loose supply lines at shower valves
- 4.complete mid wall strapping at line sets and abs stacks
- 5.remove handles from valves on supplies in concealed construction
- 6.complete clips at floor trusses
- 7.provide fire collars at ABS pipes
- 8.complete insulation at mech ducts inside units
- 9.complete separation at ceiling's that communicate with multiple units
10. provide install instruction for ATS penetration's for fire proofing at time of next inspection
11. complete draft stops at plumbing shafts and electrical panels
- 12.provide fix for damaged floor truss from truss engineer
- 13.complete all floor truss blocking
14. reattach bracing at exhaust fans duct work
15. type a units need to be reviewed prior to cover



City of Puyallup

Building Division

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

www.cityofpuyallup.org

16. complete floor rating at mech shafts
DO NOT INSULATE

Sincerely,

Kevin Spruell
Building Inspector
KSpruell@PuyallupWA.gov
(253) 841-5590