

City of Puyallup Building Division 333 S. Meridian, Puyallup, WA 98371 (253) 864-4165 www.cityofpuyallup.org

INSPECTION REPORT

Date of Inspection:	Sep 19, 2024	Inspection Result:	PARTIAL PASS
Permit Number: Property Address:	PRCNC20221036 1601 39TH AVE SE, PUY	ALLUP, WA 98374;	
Contractor:	ABSHER CONSTRUCTION CO. PO BOX 280 PUYALLUP, WA 98371-0152		
To construct:	New ~54,000 SF building containing labs, classrooms, faculty and		
	student spaces. REVISION (1) -003/21/2023 - ADDED DETAILS &		
	DESIGN REFINEMENT FROM PERMIT SET TO IFC SET OF DOCUMENTS		
	(NO CHANGE IN SQ FTG OR COST)		

On this day we have inspected your construction for **Building Final Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

Comments:

Corrections:

- 1 date of inspection 8/4/2024
 - LEVEL 1
 - 1.guard rail in hallway next to room 126 needs to be min of 42" high
 - 2. complete mono coat in electrical room 126
 - 3.complete fire stop in electrical room126
 - 4. complete mono coat in room 127
 - 5.complete fire stopping in room127
 - 6.complete electrical in ceiling in hall way by fire sprinkler riser room
 - 7.complete fire caulking in room 128
 - 8. complete junction boxes at hot water tanks room 128
 - 9.complete condensate line at mini split in room 128
 - 10. provide back flow certs
 - 11.bottom step of fire sprinkler riser stairs exceeds 7" in rise
 - 12.room 121 complete fire stopping south wall
 - 13.room 120 complete fire stopping
 - 14. complete mono coat
 - 15. room 136 complete top of wall at rated wall



City of Puyallup Building Division 333 S. Meridian, Puyallup, WA 98371 (253) 864-4165 www.cityofpuyallup.org

16.room 120 at exterior complete head of wall 17.room 104 at rated stair wall complete fire stopping and complete missing drywall 18.provide brail signage at ADA bathroom 19. complete paper towel holders per ADA at sinks DATE OF INSPECTION 8/5/2024 **STAIRS STAIRWELL 2** 1.level 0 complete 2 penetration's 2.level one mid landing guardrail needs to min of 42" high 3.level one mid landing guardrail at wall not to exceed 4" clearance at wall 4. complete handrail clearances not to be less than 1 1/2 " at landing turns **STAIRWELL 1** 1.level 3 top flight of stairs not exceed not exceed 7" in rise 2. complete handrail clearances not to be less than 1 1/2" at landing turns 3. stairs not to exceed 3/8" variance in entire flight of stairs 4. 1st floor bottom step not to exceed 7" in rise 5.complete fire taping at stair stringer level 1 DATE OF INSPECTION 9/5/2024 level 2 1.provide min 42" ht at guardrail 2.room 236 complete firestopping at rated wall 3.room 220 complete firestopping at rated wall 4.room 220 remove paper from sprinkler heads 5.room 220 complete covers on jay boxes 6.provide hammer arrestor at ice maker 7. provide backflow cert for ice maker 8. provide hammer arrestor and air gap at dishwasher 9. room 231 provide tops at window sills 10. room 208 complete fire stopping at rated stair wall at conduits and at beam 11.complets vertical grab bars in ADA stalls as discussed with contractor 12. provide brail signage at ADA stalls 2 date of inspection 9/11/2024 1. TCO granted 10 days from todays date 2. ok to occupy as discussed with contractor 3 date of inspection 9/9/2024 roof inspection 1 provide min clearance at plumbing vent to air intake at AHU 1 2.complete roof screen metal and gate 3.clean construction debris off roof 4.clean construction debris off of tops of AHU's



City of Puyallup **Building Division** 333 S. Meridian, Puyallup, WA 98371 (253) 864-4165 www.cityofpuyallup.org

- 5. install new ships ladder
- 6. this is a complete list for building final
- 4 Exterior of Building

1; paint gas pipe next to gas meter.

Level 0 - Building corrections complete (provide special inspection approval for firestopping prior to Building Final)

Level 1 - Building corrections complete.

Level 2-

1; Room 220 complete firestopping at rated wall. (ATS)

2; Room 200 complete cover plate at electrical boxes.

Level 3 -Building corrections complete.

Stairwell 2 - Building corrections complete.

Stairwell 1- complete fire tape at stair stringer of Level 1.

Roof-

- 1; provide min.10' from plumbing vent to air intake at AHU1.
- 2; complete room screen metal and gate.
- 3 ; clean construction debris off of roof.
- 4, clean construction debris off top of AHU's

Sincerely,

King

Shannon King **Building Inspector 2** ShannonK@PuyallupWA.gov (253) 840-6684