



City of Puyallup

**Building Division**

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

[www.cityofpuyallup.org](http://www.cityofpuyallup.org)

## INSPECTION REPORT

**Date of Inspection:** Oct 08, 2024

**Inspection Result:** **PARTIAL PASS**

**Permit Number:** PRCTI20240669

**Property Address:** 4102 S MERIDIAN, Unit: D, PUYALLUP, WA 98373;

**Contractor:** MRE CONSTRUCTION, LLC. 1415 CALHOUN BEND AZLE, TX 76020  
(817) 797-4928

**To construct:** TENANT INTERIOR ALTERATION, EXISTING SPACE, NEW TENANT TO  
INCLUDE NEW WALLS, FINISHES, FIXTURES, AND PAINT- BOOT BARN

On this day we have inspected your construction for **Erosion And Sediment Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

**Comments:** E&S is good as long as the straw waddles are maintained and not ran over. Keep the rolls along the sidewalk area.

All concrete washout needs to be contained.

**Corrections:**

Sincerely,

Jason Little



City of Puyallup

---

**Building Division**

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

[www.cityofpuyallup.org](http://www.cityofpuyallup.org)

Development Engineering Inspector

[JLittle@PuyallupWA.gov](mailto:JLittle@PuyallupWA.gov)

(253) 435-3636