



City of Puyallup

Building Division

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

www.cityofpuyallup.org

INSPECTION REPORT

Date of Inspection: Oct 09, 2024

Inspection Result: **FAILED**

Permit Number: PRCTI20221698

Property Address: 201 W MAIN, PUYALLUP, WA 98371;

Contractor: ALDRICH & ASSOCIATES INC. 810 240TH ST SE BOTHELL, WA 98021

To construct: Remodel of existing office building to a medical/dental clinic - CHC
CANNERY * REVISION (1) - 1/26/2024 - CORRECT OCCUPANCY, FULL
RE-ROOF AND WALL ASSEMBLIES

On this day we have inspected your construction for **Plumbing Final Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

Comments:

Corrections:

- 1 date of inspection 10/8/2024
 1. complete insulation at back flow on first floor
 - 2.room 138 complete sink to a max ht of 34"
 - 3.provide all corrected backflow certs and final letters regarding plumbing
 - 4.room 126 provide hammer arrestor at dishwasher
 - 5.room 130 complete sink to max ht of 34"
 6. room 130 provide flushometer on correct side of toilet
 7. room 109 provide flushometer on correct side of toilet
 - 8.room 109 complete sink to max ht of 34"
 - 9.room 113 complete sink to max ht of 34"
 10. room 113 provide flushometer on correct side of toilet
 - 11.room 273 complete toilet per city approved plans for wall to center of toilet 16"to 18"
 12. room 266 complete sink to max ht of 34"
 - 13.room 266 complete toilet per city approved plans for wall to center of toilet 16"to 18"
 - 14.room 230 complete toilet per city approved plans for wall to center of toilet 16"to 18"
 - 15.room 230 provide flushometer on correct side of toilet
 - 16.room 214 complete sink to max ht of 34"
 - 17.room 214 provide flushometer on correct side of toilet



City of Puyallup

Building Division

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

www.cityofpuyallup.org

18. room 148 provide install instructions for dishwasher and sterilizer on site for verification whether or not a hammer arrestor is needed

19. not a complete list

Sincerely,

Kevin Spruell
Building Inspector
KSpruell@PuyallupWA.gov
(253) 841-5590