



City of Puyallup

**Building Division**

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

[www.cityofpuyallup.org](http://www.cityofpuyallup.org)

## INSPECTION REPORT

**Date of Inspection:** Oct 10, 2024

**Inspection Result:** **FAILED**

**Permit Number:** B-20-0741

**Property Address:** 2345 W STEWART, PUYALLUP, WA 98371;

**Contractor:** RICHARD A FARRIS 2401 W STEWART PUYALLUP, WA 98371-4813  
(253) 255-3413

**To construct:** NEW SFR

On this day we have inspected your construction for **Erosion And Sediment Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

**Comments:** Track out on to W Stewart must be cleaned up ASAP.

**Corrections:**

- 1 - Silt fence along west side may need to be extended east a few feet. We will take a look after grading has been completed.
  - Silt fence along east side may need to be added. After grading and SFR import we will need to take a look.
  - Protect new septic tanks.
  - No track out. Maintain rock cleanliness during the wet months.
  - No stock piles where dispersion trenches belong.

Sincerely,

Jeff Hill  
Development Engineering Inspector  
[Jhill@PuyallupWA.gov](mailto:Jhill@PuyallupWA.gov)  
(253) 204-5633