



Building Division 333 S. Meridian, Puyallup, WA 98371 (253) 864-4165 www.cityofpuyallup.org

Date Issued	11 Oct 2024
Permit Number	PRRNSF20230919
Contractor's Name	HC HOMES INC

## INSPECTIONS REQUIRED

Fire Sprinkler Final Inspection - Fire Sprinkler Final Inspection Fire Final Inspection - Fire Final Inspection **Residential Final Inspection** - Residential Final Inspection **Plumbing Final Inspection** - Plumbing Final Inspection Mechanical Final Inspection - Mechanical Final Inspection **Engineering Final Inspection** - Engineering Final Inspection Water Service Inspection - Water Service Inspection **Underfloor Inspection** - Underfloor Inspection Soil Amendment Inspection - Soil Amendment Inspection Sidesewer Inspection - Sidesewer Inspection Shower Pan Inspection - Shower Pan Inspection Shear Wall Inspection - Shear Wall Inspection Service Backflow Inspection - Service Backflow Inspection Plumbing Rough In Inspection - Plumbing Rough In Inspection Frontage/Driveway Inspection - Frontage/Driveway Inspection Frame Inspection - Frame Inspection Foundation/Rebar Inspection - Foundation/Rebar Inspection



City of Puyallup Building Division 333 S. Meridian, Puyallup, WA 98371 (253) 864-4165 www.cityofpuyallup.org

Footing/Setback Inspection - Footing/Setback Inspection

Floodproof Certification Inspection - Floodproof Certification Inspection

Fire Sprinkler Cover Inspection - Fire Sprinkler Cover Inspection

Erosion And Sediment Inspection - Erosion And Sediment Inspection

Building Final Inspection - Building Final Inspection

Carbon Monoxide Detectors Inspection - Description

Combination Frame And Rough In Inspection - Combination Frame And Rough In Inspection

Comment Building Div Inspection - Comment Building Div Inspection

Comment Engineering Div Inspection - Comment Engineering Div Inspection

Elevation Verification Inspection - Elevation Verification Inspection

Energy (Insulation) Inspection - Energy (Insulation) Inspection

Slab/Insulation Inspection - Slab/Insulation Inspection

Storm Inspection - Storm Inspection