City of Puyallup

Engineering Division

333 S. Meridian, Puyallup, WA 98371 (253) 864-4165 www.cityofpuyallup.org

INSPECTION REPORT

Date of Inspection: Oct 16, 2024 Inspection Result: PARTIAL PASS

Permit Number: PRGR20240491

Property Address: 3112 E PIONEER, PUYALLUP, WA 98372; 911 SHAW RD, PUYALLUP, WA

98372; 901 SHAW RD, PUYALLUP, WA 98372; 813 SHAW RD, PUYALLUP,

WA 98372;

Contractor: MCKEE ENTERPRISES, LLC PO BOX 5 ENUMCLAW, WA 98022

To construct: Grading for relocation and restoration of an existing stream at the East

Town Crossing site. STREAM RELOCATION - EAST TOWN CROSSING

On this day we have inspected your construction for **Erosion And Sediment Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

Comments: McKee worked on BMP's. See corrections below, MAINTAIN.

Corrections:

- 2 Maintain ONSITE pavement cleanliness. No silt runoff into the storm.
 - Maintain silt fence.
 - Keep an eye on the storm filter vaults. If those begin to fill with silt they will need to be protected and the silt culprit will need to be stopped.


Sincerely,



City of Puyallup

Engineering Division

333 S. Meridian, Puyallup, WA 98371 (253) 864-4165 www.cityofpuyallup.org



Jason Little
Development Engineering Inspector
JLittle@PuyallupWA.gov
(253) 435-3636