

City of Puyallup **Engineering Division** 333 S. Meridian, Puyallup, WA 98371 (253) 864-4165 www.cityofpuyallup.org

## **INSPECTION REPORT**


Date of Inspection:	Oct 18, 2024	Inspection Result:	PASSED
Permit Number: Property Address:	PRUSR20241577 4102 S MERIDIAN, Unit: A, PUYALLUP, WA 98373;		
Contractor:	PIONEER PLUMB, DBA - LOYAL MECHANICAL INC 2400 NW 80TH ST #286 SEATTLE, WA 98117		
To construct:	Adding a Soil pipe connection to the existing soil pipe connection BOOT BARN		

On this day we have inspected your construction for **Job Start Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

**Comments:** Contractor installed new SS to the existing SS for the building. They disconnected the existing on the backside of the new connection. Okay to bed with crushed rock and backfill. Note: When ready to install the new SS to the north, please schedule an inspection through the portal. Install locate wire and sewer bury tape on the new SS to the north.

## Corrections:

Sincerely,





City of Puyallup **Engineering Division** 333 S. Meridian, Puyallup, WA 98371 (253) 864-4165 www.cityofpuyallup.org

Jason Little Development Engineering Inspector JLittle@PuyallupWA.gov (253) 435-3636