



City of Puyallup

**Engineering Division**

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

[www.cityofpuyallup.org](http://www.cityofpuyallup.org)

## INSPECTION REPORT

**Date of Inspection:** Oct 23, 2024

**Inspection Result:** **PARTIAL PASS**

**Permit Number:** PRUSR20241613

**Property Address:** 619 10TH ST SE, PUYALLUP, WA 98372;

**Contractor:** ABC ABLE SEPTIC 109 WASHINGTON AVE N EATONVILLE, WA 98328  
(253) 691-0770

**To construct:** Repairing approximately 33' of side sewer line between the side of the house to the property line.

On this day we have inspected your construction for **Engineering Final Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

**Comments:** Yard clean up looks good.

Question, will a carson (green or gray) c/o cover (lid with sewer) be installed on both c/o's?

**Corrections:**

Sincerely,

Jason Little

Development Engineering Inspector



City of Puyallup

---

**Engineering Division**

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

[www.cityofpuyallup.org](http://www.cityofpuyallup.org)

JLittle@PuyallupWA.gov

(253) 435-3636