



City of Puyallup

Engineering Division

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

www.cityofpuyallup.org

INSPECTION REPORT

Date of Inspection: Oct 28, 2024

Inspection Result: **FAILED**

Permit Number: PRGR20230972

Property Address:

Contractor: MCKEE ENTERPRISES, LLC PO BOX 5 ENUMCLAW, WA 98022

To construct: Early Clear, Grade, and Fill for the associated East Town Crossing Civil Permit submittal (2902 E PIONEER, PUYALLUP, WA 98372)

On this day we have inspected your construction for **Erosion And Sediment Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

Comments: - The storm run off is near breaching the temp. berm for the stream. Added BMP's must be implemented to keep the sediment laden stormwater on site and treated before discharge.
- Contractor can not use road side ditch and west box culvert as sediment control. Please see approved C,F,&G phase 1 plans for proper sediment control.
- The R-Tanks can not be used unless the sediment laden stormwater is treated. A temporary sediment pond must be established.
- All bare soil needs to be protected.
- Also see corrections below.

Corrections:

- 1 Need to install proper sediment controls per sheet C-4 of the approved plans on this permit.
No track out! Maintain spalls and keep tires clean!
Keep trucks out of mud unless there is a wheel wash.
Keep spalls on site.
Need SWPPP on site.

Sincerely,



City of Puyallup

Engineering Division

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

www.cityofpuyallup.org

Jason Little

Development Engineering Inspector

JLittle@PuyallupWA.gov

(253) 244-0387