



City of Puyallup

Engineering Division

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

www.cityofpuyallup.org

INSPECTION REPORT

Date of Inspection: Nov 04, 2024

Inspection Result: **FAILED**

Permit Number: E-20-0070

Property Address: 3601 9TH ST SW;

Contractor: THARALDSON HOSPITALITY DEV LLC 4520 36TH AVE S FARGO, ND
58104

To construct: CIVILS ~ HOMEWOOD SUITES SOUTH HILL MALL MOTEL**2021 STORM
SDC FEES UPDATED**APP EXT TO 12/30/21 BLDG PERMIT B-20-0180

On this day we have inspected your construction for **Erosion And Sediment Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

Comments: Lay down area has turned to mud. this is causing dirty water to leave the site. install bmp's around the site and stabilize soils

Corrections:

- 1 1st warning!
 1. Keep silt runoff on site.
 2. Keep silt run off from entering the existing storm on site.
 3. Protect the on site existing storm with multiple BMP's to ensure no silt enters the existing storm system. This will result in an entire surrounding site extensive storm cleaning.

Sincerely,

Jeff Hill
Development Engineering Inspector
Jhill@PuyallupWA.gov
(253) 204-5633