### City of Puyallup

#### **Building Division**

333 S. Meridian, Puyallup, WA 98371 (253) 864-4165 www.cityofpuyallup.org

## **INSPECTION REPORT**

Date of Inspection: Nov 13, 2024 Inspection Result: NOT READY

Permit Number: PRRWF20241506

**Property Address:** 707 39TH AVE SE, PUYALLUP, WA 98374;

Contractor: WALSH CONSTRUCTION CO. 315 FIFTH AVE S, SUITE 600 SEATTLE, WA

98104- (206) 547-4008

**To construct**: Installing an engineered rockery at the Wesley Homes Bradley Lake

Development The rockery is approx 315 LF long and apprx 6 to 8' tall and is shown in the civl drawings under permit #PRCCP20231028 ~ THE

ROCKERY/WESLEY HOMES BRADLEY PARK PH 2 - BROWNSTONE

On this day we have inspected your construction for **Footing/Setback Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

#### Comments:

#### Corrections:

- 1 1; provide City approved plans on-site at time of inspection.
  - 2 ; provide Geo-tech report at time of next inspection, not ready

Mannon King

- 2 1; provide City approved plans on-site at time of inspection.
  - 2 ; provide Geo-tech report and final letter at time of next inspection, not ready

Sincerely,



## City of Puyallup

# **Building Division**

333 S. Meridian, Puyallup, WA 98371 (253) 864-4165 www.cityofpuyallup.org

Shannon King Building Inspector 2 ShannonK@PuyallupWA.gov (253) 840-6684