CITY OF PUYALLUP

1100 - 39th Ave SE Puyallup, WA 98374

Phone: 253-841-5524 Fax: 253-841-5437 **Backflow Prevention Assembly Test Report**

Mailing Address

Kermit Jorgensen 1036 Valley Ave NW Puyallup, WA 98371

Account #:

Last Test: 10-23-24

ShutOff:

Test Due: 10-15-24

Service Address	Se	rvice	Add	ress
-----------------	----	-------	-----	------

Address: 1036 Valley Ave NW Puyallup, WA 98371
Company: Kermit Jorgensen
Hazard: Premise isolation

Location: Locked hotbox by meter

Serial #: 19542C

Manufacturer: Apollo Model: RPLF4A

> Type: RPZ Size: 1"

Hazard #

					mazaru #.		
	Reduced	1	RP ⊠ DC □		CDA 🗆 PDA 🗆		
	Double Check Va			PVB □ SVB □		Air Gap ☐ AVB ☐	
	Check Valve #1	Check Valve #2	Relief Valve		PVB/SVB		
Initial Test	Leaked Closed Tight X	Leaked Closed Tight X	Did not Open		AIR INLET Did not Oper	n 🔲	
	Held at 7.3 PSID	Held atPSID	Opened at 3.0	_PSID	Opened at_		_PSID
Repairs	Cleaned	Cleaned Replaced	Cleaned		CHECK VAI Leaked Held at		PSID
Details					Cleaned Replaced		
					AIR INLET Opened at_		PSID
Final Test	Closed Tight	Closed Tight Held at PSID	Opened at	PSID	CHECK VAL		DOID
Comment		Tield atFSID	Opened at	_PSID	Held at		
Line Pressure							60
Meter Reading							
				Held	d Backpressure	·	
#2 Shuto							Tight
The above report is certified to be true.					√alve Exercised	d1	alse
	Date/Time Tester	Signature	Tester#			Passe	d Failed
Initial Test	10-23-24 Josh Elliott	22 Ear	B6472		west 845-5 8211963	X	
Repairs							
Final Test							