



City of Puyallup

**Engineering Division**

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

www.cityofpuyallup.org

## INSPECTION REPORT

**Date of Inspection:** Nov 14, 2024

**Inspection Result:** **FAILED**

**Permit Number:** E-20-0070

**Property Address:** 3601 9TH ST SW;

**Contractor:** THARALDSON HOSPITALITY DEV LLC 4520 36TH AVE S FARGO, ND  
58104

**To construct:** CIVILS ~ HOMEWOOD SUITES SOUTH HILL MALL MOTEL\*\*2021 STORM  
SDC FEES UPDATED\*\*APP EXT TO 12/30/21 BLDG PERMIT B-20-0180

On this day we have inspected your construction for **Erosion And Sediment Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

**Comments:** Spoil piles and areas of soil not being work need to be covered. Due to the grading for asphalt a puddle has formed at the North West corner of the site. The water is less then a 1/2" from discharging off site. The water has a high PH and turbidity of 460NTU. If the water is discharged a Stop work order will be issued.

**Corrections:**

- 1 set up a way to keep the turbid high ph water from discharging off site.
- 2 Cover spoil piles and areas of soil that are not being actively worked.

Sincerely,

Jeff Hill  
Development Engineering Inspector  
Jhill@PuyallupWA.gov  
(253) 204-5633