#### City of Puyallup

#### **Building Division**

333 S. Meridian, Puyallup, WA 98371 (253) 864-4165 www.cityofpuyallup.org

### **INSPECTION REPORT**

Date of Inspection: Nov 18, 2024 Inspection Result: PARTIAL PASS

Permit Number: PRMU20240404

Property Address: 2902 E PIONEER, BUILDING B, PUYALLUP, WA

**Contractor:** MKM LEGACY LLC 8705 CANYON RD SUITE PUYALLUP, WA 98371 **To construct:** BUILDING G 3-story apartment building - EAST TOWN CROSSING - 2902

E PIONEER - ETC - APT BLDG G

On this day we have inspected your construction for **Erosion And Sediment Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

Comments: Please maintain, thank you.

#### Corrections:

- 1 ZERO concrete washout on the ground!
  - Maintain concrete washout bins. No pumping excess washout water to the ground.
  - ZERO track out onto Pioneer or Shaw Rd.
  - Keep on site paved areas cleaned.
  - No pumping into storm, sewer, or infiltration area.
  - Keep infiltration area south of the building clean and protect with snow fence.


Sincerely,



## City of Puyallup

# **Building Division**

333 S. Meridian, Puyallup, WA 98371 (253) 864-4165 www.cityofpuyallup.org



Jason Little
Development Engineering Inspector
JLittle@PuyallupWA.gov
(253) 244-0387