



City of Puyallup

Building Division

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

www.cityofpuyallup.org

INSPECTION REPORT

Date of Inspection: Nov 25, 2024 **Inspection Result:** **NOT READY**

Permit Number: PRMH20240593

Property Address: 1023 39TH AVE SE, PUYALLUP, WA 98374;

Contractor: HERMANSON 1221 2ND AVE N KENT, WA 98032

To construct: Phase 2 build-out of existing chilled water plant. Scope includes installation of the following fixtures: (1) Water Cooled Chiller and (1) Chilled water pump, (1) Cooling Tower and Condenser Water Pump, (1) Buffer Tank, and (1) Solid Separator. To include piping connections between new equipment to existing system.

On this day we have inspected your construction for **Mechanical Rough In Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

Comments:

Corrections:

- 1 provide test on all piping not tested at time of inspection as discussed with Todd .

Sincerely,

Shannon King
Building Inspector 2
ShannonK@PuyallupWA.gov
(253) 840-6684



City of Puyallup

Building Division

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

www.cityofpuyallup.org