



City of Puyallup

**Building Division**

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

www.cityofpuyallup.org

## INSPECTION REPORT

**Date of Inspection:** Dec 05, 2024                      **Inspection Result:**      **PARTIAL PASS**

**Permit Number:** PRCTI20240560

**Property Address:** 1023 39TH AVE SE, PUYALLUP, WA 98374;

**Contractor:** HOWARD S. WRIGHT CONSTRUCTION CO. 415 1ST AVE #400 N  
SEATTLE, WA 98109

**To construct:** Cut new floor penetrations for electrical conduit, install structural steel reinforcement around openings, install fire protection assemblies for structural steel.

On this day we have inspected your construction for **Wallboard / Drywall Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

**Comments:** drywall Inspection to check GWB Stagger around new intumescent painted channels to existing beams

**Corrections:**

Sincerely,

Shannon King  
Building Inspector 2  
ShannonK@PuyallupWA.gov  
(253) 840-6684