

City of Puyallup Building Division 333 S. Meridian, Puyallup, WA 98371 (253) 864-4165 www.cityofpuyallup.org

## **INSPECTION REPORT**

Date of Inspection:	Dec 05, 2024	Inspection Result:	PARTIAL PASS
Permit Number: Property Address:	PRMU20240404 2902 E PIONEER, BUILDI	NG G, PUYALLUP, WA	
	MKM LEGACY LLC 8705 CANYON RD SUITE PUYALLUP, WA 98371 BUILDING G 3-story apartment building - EAST TOWN CROSSING - 2902 E PIONEER - ETC - APT BLDG G		

On this day we have inspected your construction for **Sidesewer Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

Comments: Okay to backfill.


Need as-built for each SS.

Please, if possible, next time install an eccentric 6 to 4 reducer.

## Corrections:

1 1. - After plumbing has been tested and released, please plug sewer at closest sewer MH. Note: The underground contractor has tested and cleaned all of the sewer on site. Before building final, the sewer will need to be TV'ed by the building GC and any building material found in the sewer will need to be jetted and vaced.

Sincerely,





**Building Division** 333 S. Meridian, Puyallup, WA 98371 (253) 864-4165 www.cityofpuyallup.org

Jason Little Development Engineering Inspector JLittle@PuyallupWA.gov (253) 244-0387