



City of Puyallup

**Fire Prevention**

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

[www.cityofpuyallup.org](http://www.cityofpuyallup.org)

## INSPECTION REPORT

**Date of Inspection:** Dec 13, 2024

**Inspection Result:** **FAILED**

**Permit Number:** PRFS20241876

**Property Address:** 4102 S MERIDIAN, Unit: D, PUYALLUP, WA 98373;

**Contractor:** ARCHER CONSTRUCTION 7855 S 206TH ST KENT, WA 98032

**To construct:** Survey the existing fire sprinkler system and perform hydraulic calculations to see if existing system can provide Ordinary Hazard Group 2 (Merchantile) protection with the existing Fire Pump taken out of service.

On this day we have inspected your construction for **Erosion And Sediment Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

**Comments:** Due to the pre-existing fire pumps long standing fuel leak to the floor drain that possibly outlets to the storm, see corrections below.

**Corrections:**

- 1 - Verify the floor drain out to storm or sewer.
- Dilute, clean, and dry fire room floor.
- Vac and jet ALL storm along the west and north side of the building and the outlet to the swale.

Sincerely,



City of Puyallup

---

**Fire Prevention**

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

[www.cityofpuyallup.org](http://www.cityofpuyallup.org)

Jason Little  
Development Engineering Inspector  
[JLittle@PuyallupWA.gov](mailto:JLittle@PuyallupWA.gov)  
(253) 244-0387