



City of Puyallup

Fire Prevention

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

www.cityofpuyallup.org

INSPECTION REPORT

Date of Inspection: Dec 16, 2024

Inspection Result: **PASSED**

Permit Number: PRFS20241876

Property Address: 4102 S MERIDIAN, Unit: D, PUYALLUP, WA 98373;

Contractor: ARCHER CONSTRUCTION 7855 S 206TH ST KENT, WA 98032

To construct: Survey the existing fire sprinkler system and perform hydraulic calculations to see if existing system can provide Ordinary Hazard Group 2 (Merchantile) protection with the existing Fire Pump taken out of service.

On this day we have inspected your construction for **Erosion And Sediment Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

Comments: All storm has been cleaned.

There is still some garbage left in the fire room.

Corrections:

- 1 - Verify the floor drain out to storm or sewer.
- Dilute, clean, and dry fire room floor.
- Vac and jet ALL storm along the west and north side of the building and the outlet to the swale.

Sincerely,



City of Puyallup

Fire Prevention

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

www.cityofpuyallup.org

Jason Little
Development Engineering Inspector
JLittle@PuyallupWA.gov
(253) 244-0387