## City of Puyallup

## **Building Division**

333 S. Meridian, Puyallup, WA 98371 (253) 864-4165 www.cityofpuyallup.org

## INSPECTION REPORT

Date of Inspection: Dec 19, 2024 Inspection Result: FAILED

Permit Number: PRDE20241467

**Property Address:** 3303 8TH AVE SE, Unit: E, PUYALLUP, WA 98372;

Contractor: MOUNTAIN CONSTRUCTION INC. 7457 S MADISON TACOMA, WA

98409

**To construct:** Demo existing single-story farm storage building and foundation. ~

STEP BY STEP LEARNING CTR

On this day we have inspected your construction for **Erosion And Sediment Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

**Comments:** See corrections below. This will prevent any silt from entering the ditch. The 4" drain is not being used anymore and the swale does not need to be directed to the ditch without proper stabilization.

Thank you

#### **Corrections:**

- 1 Remove existing 4" drain from the ditch.
  - Fill in the swale.
  - Backfill the silt fence.


Sincerely,



## City of Puyallup

# **Building Division**

333 S. Meridian, Puyallup, WA 98371 (253) 864-4165 www.cityofpuyallup.org



Jason Little
Development Engineering Inspector
JLittle@PuyallupWA.gov
(253) 244-0387