



City of Puyallup

**Building Division**

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

www.cityofpuyallup.org

## INSPECTION REPORT

**Date of Inspection:** Dec 26, 2024                      **Inspection Result:**     **FAILED**

**Permit Number:** PRDE20241467

**Property Address:** 3303 8TH AVE SE, Unit: E, PUYALLUP, WA 98372;

**Contractor:** MOUNTAIN CONSTRUCTION INC. 7457 S MADISON TACOMA, WA 98409

**To construct:** Demo existing single-story farm storage building and foundation. ~  
STEP BY STEP LEARNING CTR

On this day we have inspected your construction for **Erosion And Sediment Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

**Comments:** Please figure out why exposed hole/pipe is leaching silt into the ditch at location of existing building drain.

Remove clean rock and bury silt fence with native material.

**Corrections:**

- 1 - Fill in the swale at silt fence with native material.  
- Backfill the silt fence with native material.

Sincerely,



City of Puyallup

---

**Building Division**

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

[www.cityofpuyallup.org](http://www.cityofpuyallup.org)

Jason Little

Development Engineering Inspector

[JLittle@PuyallupWA.gov](mailto:JLittle@PuyallupWA.gov)

(253) 244-0387