



City of Puyallup

**Building Division**

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

www.cityofpuyallup.org

## INSPECTION REPORT

**Date of Inspection:** Jan 13, 2025

**Inspection Result:** NOT READY

**Permit Number:** PRCTI20240333

**Property Address:** 1023 39TH AVE SE, PUYALLUP, WA 98374;

**Contractor:** HOWARD S WRIGHT 415 1ST AVE N SEATTLE, WA 98109

**To construct:** Interior tenant improvements to construct new UPS ROOM of 2,223 s.f.  
and new BATTERY ROOM of 1,474 s.f. - CENTERIS VOLTAGE PARK

On this day we have inspected your construction for **Frame Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

**Comments:** called in wrong permit number for inspection.

**Corrections:**

1. framing of opening for electrical at battery room approved

Sincerely,

Shannon King  
Building Inspector 2  
ShannonK@PuyallupWA.gov  
(253) 840-6684