

City of Puyallup Building Division 333 S. Meridian, Puyallup, WA 98371 (253) 864-4165 www.cityofpuyallup.org

INSPECTION REPORT

Date of Inspection:	Jan 16, 2025	Inspection Result:	NOT READY
Permit Number: Property Address:	PRCTI20241387 1023 39TH AVE SE, PUYA	ALLUP, WA 98374;	
Contractor:	HOWARD S. WRIGHT CONSTRUCTION CO. 415 1ST AVE #400 N		
	SEATTLE, WA 98109		
To construct:	Relocate existing underground utilities, construct new retaining walls,		
	equipment pads, and install exterior and interior mechanical equipment. - CENTERIS VOLTAGE PARK		

On this day we have inspected your construction for **Plumbing Below Slab Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

Comments: engineering inspection, called in error.

Corrections:

Sincerely,

King

Shannon King Building Inspector 2 ShannonK@PuyallupWA.gov (253) 840-6684