

City of Puyallup Building Division 333 S. Meridian, Puyallup, WA 98371 (253) 864-4165 www.cityofpuyallup.org

INSPECTION REPORT

Date of Inspection:	Feb 10, 2025	Inspection Result:	NOT READY
Permit Number: Property Address:	PRMU20230881 707 39TH AVE SE, Unit: [), PUYALLUP, WA 98374;	
Contractor:	Anthony Mizin 315 fifth		
	CONSTRUCTION CO. 31 (206) 547-4008	5 FIFTH AVE S, SUITE 600) SEATTLE, WA 98104-
To construct:		evelopment of Wesley Br	adley Park, - Group R2
	w/ 3 stories Type VA over Type 1A concrete garage. This project has 67		
	dwelling units WESLEY HOMES BRADLEY PARK PH 2 - BROWNSTONE		

On this day we have inspected your construction for **Footing/Setback Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

Comments:

Corrections:

- 1 1 ; complete all rebar as per city approved plans.
 2 ; provide min. 3" from soil to rebar,min. bar lap,and corner bars as discussed with contractor. (not ready)
 - 3; ok to pour with special inspectors approval.

Sincerely,

non King

Shannon King Building Inspector 2



City of Puyallup Building Division 333 S. Meridian, Puyallup, WA 98371 (253) 864-4165 www.cityofpuyallup.org

ShannonK@PuyallupWA.gov (253) 840-6684