



City of Puyallup

**Building Division**

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

www.cityofpuyallup.org

## INSPECTION REPORT

**Date of Inspection:** Feb 13, 2025                      **Inspection Result:**     **PARTIAL PASS**

**Permit Number:** PRCNC20241741

**Property Address:** 1023 39TH AVE SE, PUYALLUP, WA 98374;

**Contractor:** HOWARD S WRIGHT CONSTRUCTORS 501 EASTLAKE AVE E, SEATTLE, WA 98109

**To construct:** Construct new 625 s.f. metal switchgear building and install (5) 1,250 kW standby diesel generators with (5) integral 7,300 gallon above ground fuel storage tanks. - CENTERIS SOUTH SWITCH GEAR BUILDING & GENERATORS

On this day we have inspected your construction for **Shear Wall Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

**Comments:** south side of switch gear building shear complete except at south west corner. (ok to cover with special inspection)

**Corrections:**

Sincerely,

Shannon King  
Building Inspector 2  
ShannonK@PuyallupWA.gov  
(253) 840-6684



City of Puyallup

---

**Building Division**

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

[www.cityofpuyallup.org](http://www.cityofpuyallup.org)