



City of Puyallup

Building Division

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

www.cityofpuyallup.org

INSPECTION REPORT

Date of Inspection: Feb 19, 2025

Inspection Result: **PARTIAL PASS**

Permit Number: PRCNC20241741

Property Address: 1023 39TH AVE SE, PUYALLUP, WA 98374;

Contractor: HOWARD S WRIGHT CONSTRUCTORS 501 EASTLAKE AVE E, SEATTLE, WA 98109

To construct: Construct new 625 s.f. metal switchgear building and install (5) 1,250 kW standby diesel generators with (5) integral 7,300 gallon above ground fuel storage tanks. - CENTERIS SOUTH SWITCH GEAR BUILDING & GENERATORS

On this day we have inspected your construction for **Wallboard / Drywall Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

Comments: Screw inspection complete for (densglass / densarmor plus) at south wall of switchgear building.

Corrections:

Sincerely,

Shannon King
Building Inspector 2
ShannonK@PuyallupWA.gov
(253) 840-6684



City of Puyallup

Building Division

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

www.cityofpuyallup.org