



City of Puyallup

**Building Division**

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

[www.cityofpuyallup.org](http://www.cityofpuyallup.org)

## INSPECTION REPORT

**Date of Inspection:** Feb 19, 2025

**Inspection Result:** **FAILED**

**Permit Number:** PRCTI20242004

**Property Address:** 1023 39TH AVE SE, PUYALLUP, WA 98374;

**Contractor:** HOWARD S. WRIGHT CONSTRUCTION CO. 415 1ST AVE #400 N  
SEATTLE, WA 98109

**To construct:** Construct 6,594 s.f. interior server room tenant improvement within  
existing data center space including structural rack bracing and  
mechanical support and mechanical equipment and piping. - CENTERIS

On this day we have inspected your construction for **Frame Inspection** and we find the following  
result of the inspection. If there are any questions, please contact the inspector below.

**Comments:**

**Corrections:**

- 1 frame inspection of new Data Hall.
  - 1 ; provide electrical cover approval.
  - 2 ; provide 3/4" gap at top deflection track as per approved plans.

Sincerely,

Shannon King  
Building Inspector 2  
[ShannonK@PuyallupWA.gov](mailto:ShannonK@PuyallupWA.gov)  
(253) 840-6684



City of Puyallup

---

**Building Division**

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

[www.cityofpuyallup.org](http://www.cityofpuyallup.org)