


Meridian Firs Apartments





Deck Repair




City of Puyallup **Project Statistics Building** CODE COMPLIANCE: 2021 INTERNATIONAL EXIST BLDG CODE **REVIEWED FOR** 2923 S. MERIDIAN ST (BLDG D) SITE ADDRESS: PUYALLUP, WA COMPLIANCE 0419032096 SKinnear R-2 OCCUPANCY MULTI-FAMILY 2 STORY APARTMENTS 02/12/2025 1:30:56 PM NUMBER OF DECKS: 6 DECKS









| Project Team

MERIDIAN FIRS LLC C/O DMCI PO BOX 111088 TACOMA, WA 98411 (253) 475-2405

DEARTH@DMCIMAIL.COM ARCHITECT: CASEY + DeCHANT ARCHITECTS, LLC PO BOX 456

> PUYALLUP, WA 98371 (253) 584-5207 CELL 253-677-0364 LARRY DeCHANT

LDECHANT@CASEYDECHANTARCH.COM SOLUTIONS 4 STRUCTURES, INC. 11605 135TH ST. CT. E.

PUYALLUP, WA 983742 (253) 314-9822 TOMOSOLUTIONS4STRUCTURES.COM

Scope of Work

ENGINEER:

PROVIDE 42" HIGH PHYSICAL BARRIER AT SLIDING GLASS DOOR

- TO PREVENT TENANT ACCESS TO EXTERIOR DURING
- REMOVE CORNER OF EXISTING CONCRETE PATIOS AS NEEDED FOR NEW FOOTINGS WHERE CALLED OUT.
 POUR NEW CONCRETE FOOTINGS PER DETAILS AT NEW POST
- LOCATIONS WHERE CALLED OUT. ADD NEW BEAM & POSTS PER DETAILS WHERE CALLED OUT.
- NO REPLACEMENT OF DOORS, WINDOWS, CONC. PATIOS, WALKS PROPOSED OR SCHEDULED.

<u>NTERIOR WORK</u> 1. NO INTERIOR WORK PROPOSED.

Drawing Notes

FOLLOW THE CONSTRUCTION DETAILS IN THE ATTACHED CONSTRUCTION DOCUMENT. HIDDEN OR UNKNOWN DEFECTS ARE NOT ADDRESSED IN THIS DOCUMENT.

BY USING THE CONSTRUCTION DOCUMENTS, CONTRACTOR SITE OBSERVATIONS AND FIELD MEASUREMENTS.

PROVIDE DEMOLITION OF EXISTING MATERIALS AS REQUIRED TO COMPLETE THE SCOPE OF WORK AND AS OUTLINED IN THE CONSTRUCTION DOCUMENTS. LEGALLY DISPOSE OF ALL

INFORMATION SHOWN IN CONSTRUCTION DOCUMENTS IS SUBJECT TO THE REVIEW AND APPROVAL OF THE THE CONTRACTOR SHALL DETERMINE THE EXACT LOCATION


OF ALL EXISTING UTILITIES BEFORE COMMENCING WORK AND AGREES TO BE FULLY RESPONSIBLE FOR ANY AND ALL DAMAGES THAT INCUR DUE TO THE CONTRACTORS FAILURE TO LOCATE EXACTLY AND PRESERVE ANY AND ALL UNDERGROUND UTILITIES.

Owner/Contractor Coordination Notes

THE FOLLOWING NOTES SHALL SERVE AS A GUIDE TO THE CONTRACTOR TO VERIFY E THE ITEMS OUTLINED BELOW ARE NOT INTENDED TO BE AN EXHAUSTIVE ANALYSIS OF POSSIBLE AREAS OF CONCERN OR CONFLICT, BUT RATHER TO SERVE AS A BEGINNING

REVIEW SPECIFICATION, MANUFACTURER'S PRODUCT LITERATURE, AND GENERAL NOTE

- SEALANT PRESSURE TREATED LUMBER METAL STRUCTURAL HANGERS, CLIPS, STRAPS, ETC MEMBRANE FLASHING
 WEATHER RESISTANT BARRIER
- REVIEW LOCAL & STATE JURISDICTIONAL REQUIREMENTS FOR COMPLETE INSTALLATIONS OF THE FOLLOWING: A. CONCRETE FOOTINGS
- STRUCTURAL INSPECTIONS IF SPECIAL STRUCTURAL INSPECTIONS ARE REQUIRED BY IBC AND/OR THE CITY OF
- DRAWINGS PREPARED BY OTHERS ARE CONSIDERED ADDITIVE TO THE ARCHITECTUR



Photos of Existing Conditions

Casey + DeChant Architects, LLC Architecture And Planning

