



City of Puyallup

**Building Division**

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

[www.cityofpuyallup.org](http://www.cityofpuyallup.org)

## INSPECTION REPORT

**Date of Inspection:** Mar 03, 2025

**Inspection Result:** **FAILED**

**Permit Number:** PRCA20241630

**Property Address:** 110 9TH AVE SW

**Contractor:** ABSHER CONSTRUCTION PO BOX 280 PUYALLUP, WA 98371-0152

**To construct:** INSTALL A FOUNTAIN IN GOLD GATE PLAZA \* REVISION (1) - 2/19/2025  
- ADD (2) 30' FLAG POLE & (1) 40' FLAG POLE, PROVIDE MODIFIED  
FOUNTAIN PIPING DRAWING

On this day we have inspected your construction for **Mechanical Rough In Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

**Comments:** contractor called for plumbing rough-in inspection.

**Corrections:**

1 1 ; plumbing not on test at time of inspection.

Sincerely,

Shannon King  
Building Inspector 2  
[ShannonK@PuyallupWA.gov](mailto:ShannonK@PuyallupWA.gov)  
(253) 840-6684