



City of Puyallup

Building Division

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

www.cityofpuyallup.org

INSPECTION REPORT

Date of Inspection: Mar 06, 2025 **Inspection Result:** **PARTIAL PASS**

Permit Number: PRMH20240831

Property Address: 1023 39TH AVE SE, PUYALLUP, WA 98374;

Contractor: HERMANSON 1221 2ND AVE N KENT, WA 98032

To construct: Installation of fuel oil pump piping - CENTERIS VOLTAGE PARK *
REVISION (1) 11/20/2024 - DIFFERENTIATED FUEL OIL SUPPLY, ADDED
CRITERIA FOR THE FUEL TANK STORAGE AND FILL, REVISED POC,
ADDED FUEL SYSTEM STORAGE TANK PIPING DIAGRAM

On this day we have inspected your construction for **Mechanical Rough In Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

Comments: 1 ; test approved at 45 psi at generator 2&3 fuel oil supply & return.

Corrections:

Sincerely,

Shannon King
Building Inspector 2
ShannonK@PuyallupWA.gov
(253) 840-6684