



City of Puyallup

Building Division

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

www.cityofpuyallup.org

INSPECTION REPORT

Date of Inspection: Mar 12, 2025 **Inspection Result:** **FAILED**

Permit Number: PRCTI20250140

Property Address: 401 15TH AVE SE, PUYALLUP, WA 98372;

Contractor: SELLEN CONSTRUCTION CO. INC PO BOX 9970 SEATTLE, WA 98109-9970

To construct: To replaces an existing X-Ray Imaging Machine in the ER on Level 1 /Dally Tower. To includes revised mechanical, electrical and structural connections for new equipment, along with wall finish upgrades and a resized entry door at Room M180.5. New Door will be provided with lead shielding as required per Medical Physicist report. Project is being reviewed by WA DOH under CRS#61639776.

On this day we have inspected your construction for **Frame Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

Comments:

Corrections:

- 1 1 ; provide lead shielding report from physicist at time of inspection.
- 2 ; complete lead shielding at door frame as per city approved plans.
not ready

Sincerely,

Shannon King



City of Puyallup

Building Division

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

www.cityofpuyallup.org

Building Inspector 2

ShannonK@PuyallupWA.gov

(253) 840-6684