



City of Puyallup

Building Division

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

www.cityofpuyallup.org

INSPECTION REPORT

Date of Inspection: Mar 13, 2025 **Inspection Result:** **PARTIAL PASS**

Permit Number: PRMU20230881

Property Address: 707 39TH AVE SE, Unit: D, PUYALLUP, WA 98374;

Contractor: Anthony Mizin 315 fifth Ave S. Suite 600 Seattle, WA 98104 WALSH CONSTRUCTION CO. 315 FIFTH AVE S, SUITE 600 SEATTLE, WA 98104- (206) 547-4008

To construct: As part of the Phase 2 development of Wesley Bradley Park, - Group R2 w/ 3 stories Type VA over Type 1A concrete garage. This project has 67 dwelling units. - WESLEY HOMES BRADLEY PARK PH 2 - BROWNSTONE

On this day we have inspected your construction for **Sanitary Sewer Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

Comments: -Inspected sewer from existing stub on north end of BLDG site to temporary plumber riser inside of Brownstone BLDG footprint. Plumbing contractor installed a ten foot riser for a water test. Observed water head pressure test for 15 min. Held tight. Contractor removed blowup test plug and released water.

-Per contractor O/W separator location is changing from outside of the north end of the BLDG to the inside of the BLDG. This has not been approved yet.

-Contractor needs to work with Engineer of Record to submit a Plan Change Request for Civil permit # PRCCP20231028 for O/W separator location change.

-Contractor also needs to work with Building Inspector for O/W separator location change.

Corrections:

Sincerely,



City of Puyallup

Building Division

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

www.cityofpuyallup.org

Michael Rosenau

Development Engineering Inspector

MRosenau@PuyallupWA.gov

(253) 344-6753