

City of Puyallup Building Division 333 S. Meridian, Puyallup, WA 98371 (253) 864-4165 www.cityofpuyallup.org

 Date Issued
 20 Mar 2025

 Permit Number
 PRCTI20250145

 Contractor's Name
 SELLEN CONSTRUCTION CO. INC

## INSPECTIONS REQUIRED

Planning Final Inspection - Planning Final Inspection Fire Final Inspection - Fire Final Inspection Mechanical Final Inspection - Mechanical Final Inspection **Engineering Final Inspection** - Engineering Final Inspection Wallboard / Drywall Inspection - Wallboard / Drywall Inspection Shear Wall Inspection - Shear Wall Inspection **Roof Sheathing Inspection** - Roof Sheathing Inspection Medical Gas Inspection - Medical Gas Inspection Mechanical Rough In Inspection - Mechanical Rough In Inspection Light Test For Grease Duct Inspection - Light Test For Grease Duct Inspection Hydrostatic Test 200Lbs 2Hrs - Hydrostatic Test 200Lbs 2Hrs Hydronic Piping Inspection - Hydronic Piping Inspection Gas Test Inspection - Gas Test Inspection Frame Inspection - Frame Inspection Foundation/Rebar Inspection - Foundation/Rebar Inspection Footing/Setback Inspection - Footing/Setback Inspection Firewall/Firestop Inspection - Firewall/Firestop Inspection



City of Puyallup Building Division 333 S. Meridian, Puyallup, WA 98371 (253) 864-4165 www.cityofpuyallup.org

Fire Or Smoke Damper Inspection - Fire Or Smoke Damper Inspection
Exit Lighting Test Inspection - Exit Lighting Test Inspection
Exhaust/Vent Fans Inspection - Exhaust/Vent Fans Inspection
Exhaust Hood Inspection - Exhaust Hood Inspection
Building Final Inspection - Building Final Inspection
Ceiling Grid/T-Bar Inspection - Ceiling Grid/T-Bar Inspection
Combination Frame And Rough In Inspection - Combination Frame And Rough In Inspection
Comment Building Div Inspection - Comment Building Div Inspection
Comment Engineering Div Inspection - Comment Engineering Div Inspection
Emergency Radio Test Review Inspection - Emergency Radio Test Review Inspection
Refrigeration Line Test Inspection - Refrigeration Line Test Inspection
Slab/Insulation Inspection - Slab/Insulation Inspection