



City of Puyallup

**Building Division**

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

[www.cityofpuyallup.org](http://www.cityofpuyallup.org)

## INSPECTION REPORT

**Date of Inspection:** Mar 20, 2025

**Inspection Result:** **PARTIAL PASS**

**Permit Number:** PRCTI20242004

**Property Address:** 1023 39TH AVE SE, PUYALLUP, WA 98374;

**Contractor:** HOWARD S. WRIGHT CONSTRUCTION CO. 415 1ST AVE #400 N  
SEATTLE, WA 98109

**To construct:** Construct 6,594 s.f. interior server room tenant improvement within  
existing data center space including structural rack bracing and  
mechanical support and mechanical equipment and piping. - CENTERIS

On this day we have inspected your construction for **Mechanical Rough In Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

**Comments:** test approved at 100 psi as noted on sheet M.F.P.203 of city approved plans.

**Corrections:**

Sincerely,

Shannon King  
Building Inspector 2  
[ShannonK@PuyallupWA.gov](mailto:ShannonK@PuyallupWA.gov)  
(253) 840-6684