



City of Puyallup

Engineering Division

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

www.cityofpuyallup.org

INSPECTION REPORT

Date of Inspection: Mar 24, 2025

Inspection Result: **FAILED**

Permit Number: PRGR20230972

Property Address:

Contractor: MCKEE ENTERPRISES, LLC PO BOX 5 ENUMCLAW, WA 98022

To construct: Early Clear, Grade, and Fill for the associated East Town Crossing Civil
Permit submittal (2902 E PIONEER, PUYALLUP, WA 98372)

On this day we have inspected your construction for **Erosion And Sediment Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

Comments: - A noticeable silt discharge to the stream from both sides of the construction entrance. The silt discharge made it's way to the west box culvert inlet. The same silt discharge made it's way to the Deer creek inlet on the NW corner of Shaw and Pioneer.

Note: I notified Randal, the CESCL for the site and the city's storm specialist Jon G.

Corrections:

- 1 1. - Install proper sized sediment control pond!
 2. - Install swales w/check dams!
 3. - Add secondary swale across spalled entrance just south of the first one. (Accumulated standing water)
 4. - Slope grade away from all areas of the silt fence.
 5. - Notify CESCL when a discharge has occurred.
- Maintain sediment controls.
No track out! Maintain spalls and keep tires clean!
Keep trucks out of mud unless there is a wheel wash.
Keep spalls on site.
Maintain SWPPP on site.
Absolutely NO concrete washout on the ground.

Sincerely,



City of Puyallup

Engineering Division

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

www.cityofpuyallup.org

Jason Little

Development Engineering Inspector

JLittle@PuyallupWA.gov

(253) 244-0387