



City of Puyallup

Building Division

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

www.cityofpuyallup.org

INSPECTION REPORT

Date of Inspection: Apr 17, 2025

Inspection Result: **PARTIAL PASS**

Permit Number: PRMH20240831

Property Address: 1023 39TH AVE SE, PUYALLUP, WA 98374;

Contractor: HERMANSON 1221 2ND AVE N KENT, WA 98032

To construct: Installation of fuel oil pump piping - CENTERIS VOLTAGE PARK *
REVISION (1) 11/20/2024 - DIFFERENTIATED FUEL OIL SUPPLY, ADDED
CRITERIA FOR THE FUEL TANK STORAGE AND FILL, REVISED POC,
ADDED FUEL SYSTEM STORAGE TANK PIPING DIAGRAM * REVISION (2)
- 3/18/2025 - ADD (7) NEW GENERATORS FOR A TOTAL OF (10) NEW
GENERATORS. INCLUDES SOO, UPDATED EQUIPMENT SCHEDULE AS
WELL AS CONTROLS DRAWINGS.

On this day we have inspected your construction for **Mechanical Rough In Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

Comments: test approved at 45 psi at generator 1 only

Corrections:

Sincerely,

Shannon King

Building Inspector 2

ShannonK@PuyallupWA.gov

(253) 840-6684



City of Puyallup

Building Division

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

www.cityofpuyallup.org