



City of Puyallup

Building Division

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

www.cityofpuyallup.org

INSPECTION REPORT

Date of Inspection: Apr 22, 2025

Inspection Result: **PARTIAL PASS**

Permit Number: PRCTI20242004

Property Address: 1023 39TH AVE SE, PUYALLUP, WA 98374;

Contractor: HOWARD S. WRIGHT CONSTRUCTION CO. 415 1ST AVE #400 N
SEATTLE, WA 98109

To construct: Construct 6,594 s.f. interior server room tenant improvement within
existing data center space including structural rack bracing and
mechanical support and mechanical equipment and piping. - CENTERIS

On this day we have inspected your construction for **Wallboard / Drywall Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

Comments: drywall nailing repair complete in room 310.

Corrections:

Sincerely,

Shannon King
Building Inspector 2
ShannonK@PuyallupWA.gov
(253) 840-6684