



City of Puyallup

**Building Division**

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

[www.cityofpuyallup.org](http://www.cityofpuyallup.org)

## INSPECTION REPORT

**Date of Inspection:** Apr 25, 2025

**Inspection Result:** **PARTIAL PASS**

**Permit Number:** PRCTI20241387

**Property Address:** 1023 39TH AVE SE, PUYALLUP, WA 98374;

**Contractor:** HOWARD S. WRIGHT CONSTRUCTION CO. 415 1ST AVE #400 N  
SEATTLE, WA 98109

**To construct:** Relocate existing underground utilities, construct new retaining walls,  
equipment pads, and install exterior and interior mechanical equipment.  
- CENTERIS VOLTAGE PARK

On this day we have inspected your construction for **Mechanical Rough In Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

**Comments:** test approved at 100 psi as noted on sheet - (P,FT.102 ) of city approved plans.

**Corrections:**

Sincerely,

Shannon King  
Building Inspector 2  
[ShannonK@PuyallupWA.gov](mailto:ShannonK@PuyallupWA.gov)  
(253) 840-6684