



City of Puyallup

Engineering Division

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

www.cityofpuyallup.org

INSPECTION REPORT

Date of Inspection: May 08, 2025

Inspection Result: **FAILED**

Permit Number: PRCCP20240808

Property Address: 911 SHAW RD, PUYALLUP, WA 98372; 901 SHAW RD, PUYALLUP, WA 98372; 813 SHAW RD, PUYALLUP, WA 98372;

Contractor: MCKEE ENTERPRISES, LLC PO BOX 5 ENUMCLAW, WA 98022

To construct: Phase 2 site development of East Town Crossing including grading, storm drainage, parking, and utilities per plans. - 731 SHAW RD

On this day we have inspected your construction for **Engineering Daily Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

Comments: McKee TV'ed the sewer for phase 2 and a portion from phase 1.

- TV from SSMH16 to SSMH17 (PASSED)

- TV from SSMH15 to SSMH16 needs to be re-TV'ed. The TV results showed ponding over 10% of the run. 28LF of total ponding out of a 7LF run.

*Please see City of Puyallup Design Standards Part 1 Section 400 (406.4 Television Inspection / Television Inspection Acceptance Criteria)

- TV from SSMH14 to SSMH15 was dirty and need to be cleaned and re-TV'ed.

- TV from phase 1 SSMH1 to phase 2 SSMH14 failed with multiple ponding's from 1/4" to 1". This need to be repaired and re-TV'ed.

Corrections:

Sincerely,



City of Puyallup

Engineering Division

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

www.cityofpuyallup.org

Jason Little

Development Engineering Inspector

JLittle@PuyallupWA.gov

(253) 244-0387