



City of Puyallup

Engineering Division

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

www.cityofpuyallup.org

INSPECTION REPORT

Date of Inspection: Jun 18, 2025

Inspection Result: **FAILED**

Permit Number: PRFUP20242000

Property Address: 1006 39TH AVE SE, PUYALLUP, WA 98374;

Contractor: MASTEC NORTH AMERICA INC 806 Douglas Rd #1100 Coral Gables, FL 33134

To construct: PERMIT EXT TO 10/26/2025 JB0002053977 COMCAST PROPOSES EXISTING POLES AND POLE TRANSFER

On this day we have inspected your construction for **Engineering Final Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

Comments: Also see inspection report of 6/13 sent to applicant.

CORRECTION: Need erosion control for disturbed areas and slope stabilization through grading, topsoil and seed along all trenched areas as well as jute mat or other means to protect the slope. Schedule this restoration as traffic control is required.

Corrections:

Sincerely,

Cheryl Trimble
Development Engineering Inspector
CTrimble@PuyallupWA.gov
(253) 290-9834