

City of Puyallup Building Division 333 S. Meridian, Puyallup, WA 98371 (253) 864-4165 www.cityofpuyallup.org

INSPECTION REPORT

Date of Inspection:	Jul 18, 2025	Inspection Result:	FAILED
Dama it Nama kan			
Permit Number:	PRC1120250103		
Property Address:	2511 INTER AVE, PUYALLUP, WA 98372;		
Contractor:	MOUNTAIN CONSTRUCTION 3411 90TH ST S; SUITE A LAKEWOOD,		
	WA 98499 (253) 474-52	81	
To construct:	Remodel of this warehouse was accomplished before being approved by		
	the City of Puyallup. A full review and inspection must be accomplished		
	by the City of Puyallup. What must be added is a full sprinkler system for		
	the warehouse, office area and mezzanine. All restrooms must be		
	brought up to code. The parts area must be brought up to structural		
	compliance.		

On this day we have inspected your construction for **Underfloor Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

Comments:

Corrections:

1 1; complete toilet to be min. 16"-18" max. from wall to center line of toilet as discussed with contractor. (inspection for below slab plumbing rough-in)

Sincerely,

Shannon King Building Inspector 2

2 King



City of Puyallup Building Division 333 S. Meridian, Puyallup, WA 98371 (253) 864-4165 www.cityofpuyallup.org

ShannonK@PuyallupWA.gov (253) 840-6684