



City of Puyallup

Building Division

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

www.cityofpuyallup.org

INSPECTION REPORT

Date of Inspection: Aug 12, 2025

Inspection Result: **PASSED**

Permit Number: PRDB20251015

Property Address: 110 9TH AVE SW, Unit: 10, PUYALLUP, WA 98371;

Contractor: ABSHER CONSTRUCTION PO BOX 280 PUYALLUP, WA 98371-0152

To construct: Post replacement from vehicle damage - DURIS BUILDING - PROVIDE
ENGINEERING DRAWING FOR FIELD INSPECTIONS

On this day we have inspected your construction for **Shear Wall Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

Comments:

Corrections:

Sincerely,

James LaVergne

JLaVergne@PuyallupWA.gov

(253) 841-5590