City of Puyallup

Building Division

333 S. Meridian, Puyallup, WA 98371 (253) 864-4165 www.cityofpuyallup.org

INSPECTION REPORT

Date of Inspection: Aug 25, 2025 Inspection Result: FAILED

Permit Number: PRMU20230881

Property Address: 707 39TH AVE SE, Unit: D, PUYALLUP, WA 98374;

Contractor: Anthony Mizin 315 fifth Ave S. Suite 600 Seattle, WA 98104 WALSH

CONSTRUCTION CO. 315 FIFTH AVE S, SUITE 600 SEATTLE, WA 98104-

(206) 547-4008

To construct: As part of the Phase 2 development of Wesley Bradley Park, - Group R2

w/ 3 stories Type VA over Type 1A concrete garage. This project has 67 dwelling units. - WESLEY HOMES BRADLEY PARK PH 2 - BROWNSTONE * REVISION (1) - 6/24/2025 - ENERGY CODE CALS, EV CAR LOCATION

AND GARAGE AND DAS SYSTEM LOCATION.

On this day we have inspected your construction for **Wallboard / Drywall Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

Comments:

Corrections:

- 1 1. Several sheetrock seams not mudded and taped.
 - 2. Provide engineering approval for PT deck bust out at stairwell.
 - 3. Provide 1" air gap for complete length of wall.

Sincerely,

James LaVergne JLaVergne@PuyallupWA.gov (253) 841-5590